

TENTATIVE AGENDA

SPECIAL CITY COUNCIL MEETING
CITY COUNCIL CHAMBERS
105 E CENTER STREET, SIKESTON
Friday, May 6, 2022
7:30 A.M.

- I. CALL TO ORDER
- II. RECORD OF ATTENDANCE
- III. OPENING PRAYER
- IV. PLEDGE OF ALLEGIANCE
- V. ITEMS OF BUSINESS
 - A. Authorize the Purchase of a Used 2002 E-One Hurricane 95' Platform Ladder Fire Apparatus
 - B. Other Items as May Be Determined During the Course of the Meeting
- VI. ADJOURNMENT

Dated this 4th day of May 2022

Rhonda Council, City Clerk

Council Letter

Date of Meeting: 22-05-06

Originating Department: Department of Public Safety

To the Mayor and City Council:

Subject:

Purchase of 2002 E-One 95' platform aerial apparatus.

Attachments:

1. Quote for the project.

Action Options:

1. Request approval to proceed with quoted project.

Background:

Sikeston DPS is requesting we enter a purchase agreement with Brindlee Mountain Fire Apparatus to purchase the following:

- 2002 E-One 95-foot platform aerial platform
- \$185,000 with Brindlee Mountain paying to have apparatus pump tested, aerial certified, pump packing and aerial controls repaired. These repairs will be completed by Banner Fire.
- Mileage is 34,000
- Overall condition is good.

This apparatus will replace the 2001 E-One ladder that was involved in an accident and totaled by our insurance. We received \$100,017.50 settlement from the insurance from this incident. There are currently limited good used apparatus on the market, and we felt this one is best fitted for our needs. This apparatus will help our overall ISO score and should serve the city until roughly 2027 or longer. We have prior knowledge with E-One apparatus and would like to stay with this brand.

BRINDLEE



MOUNTAIN

FIRE APPARATUS

Sales Agreement

Brindlee Mountain Fire Apparatus (Seller) hereby agrees to sell one 2002 E-One Hurricane 95' Platform (Apparatus) to City of Sikeston, MO (Buyer) for the sum of \$185,000.00 (One Hundred Eighty Five Thousand Dollars and no cents).

Apparatus: 2002 E-One Hurricane 95' Platform, Stock #12002, VIN: 4EN3ABA8621004741

Buyer Info: City of Sikeston, 105 E. Center St., Sikeston, MO 63801

Seller Info: Brindlee Mountain Fire Apparatus, 15410 Highway 231, Union Grove, AL 35175

Terms and Conditions of Sale:

(1) Services Included: Seller will complete all items listed on the attached Addendum.

(2) Payment and Title: Buyer will submit a 25% down payment of the sales price at the execution of this sales agreement. Buyer will make payment in full to Seller prior to the release of Apparatus for pick up or delivery. Seller will provide title free of lien to Buyer following receipt of payment.

(3) FOB Seller, Freight Collect: Buyer assumes the responsibility of the Apparatus upon pick up by carrier or other designated representative. Seller is responsible for all freight charges.

(4) Jurisdiction: This contract shall be governed by, construed, and enforced in accordance with the laws of Alabama. The undersigned by execution and delivery of this Agreement do hereby submit to the exclusive jurisdiction and venue of the state and federal courts of Marshall County, Alabama.

This agreement is valid for execution by May 6, 2022.

A handwritten signature in black ink, appearing to read 'S. T. W.', written over a horizontal line.

Sales Representative
Brindlee Mountain Fire Apparatus

5/3/2022

Date

A simple black rectangular box, intended for the signature of the authorized representative, positioned above a horizontal line.

Authorized Representative
City of Sikeston, MO

Date

BRINDLEE



MOUNTAIN

FIRE APPARATUS

Addendum to May 6, 2022 Sales Agreement

Addendum A for the contract between Brindlee Mountain Fire Apparatus (Seller) and City of Sikeston, MO (Buyer). This addendum names the specific items to be completed on the Apparatus (Stock #12002) by the Seller.

1. Apparatus will pass a new annual pump service test
2. Apparatus will have a new 3rd party aerial certification
3. The problem causing the water leak from the pump packing will be repaired
4. The problem causing the aerial controls to not function correctly at the pedestal will be repaired